Date: User: Tuesday, 30/09/2008 10:01:51 AM

Julie Lecocq

Process Sheet

Customer

: CU-DAR001 Dart Helicopters Services

Job Number **Estimate Number**

: 42353 : 10829

P.O. Number

This Issue

: 30/09/2008

: NC

: // : 40781

S.O. No. :

: MACHINED PARTS

Type

: D28931

Drawing Number

Drawing Name

Part Number

: D2893 REV B

: 02.750 SUPPORT

Project Number Drawing Revision

: B Material

: 10/10/2008

: N/A

Qty:

20 Um:

Each

Written By

Prsht Rev.

First Issue

Previous Run

Checked & Approved By

Comment

Reformat; Added P/O KJ : Est: C 02.11.26

est D 06.04.19

removed alodine

Est Rev:E Added priming as per Rev B 07-04-30 JLM

est F 08.03.19 Re-format EC verified by: DD

EC

Due Date

Est Rev:G 08-05-15 add QC14 DD verified by:EC

Additional Product

Job Number:



Seq. #:

Machine Or Operation:

Description:

1.0 DSK078

D2893-1 TURNING DETAIL



Comment: Qty.:

0.5000 Each(s)/Unit

Total: 10.0000 Each(s)

D2893-1 TURNING DETAIL

Batch: B42259

HAAS CNC VERTICAL MACHINING #1

2.0

HAAS1

Machine as per Folio FA081

Tumble & Deburr

3.0 QC2 INSPECT PARTS AS THEY COME OFF MACHINE



Comment: HAAS 1

Comment: INSPECT ALL DIM TO DIM SHEET

4.0

QC8

SECOND CHECK



Comment: SECOND CHECK



5.0

POWDER COATING

POWDER COATING

Comment: POWDER COATING

Powder Coat White Gloss (Ref: 4.3.5.1) as per QSI 005 4.3

Mask Inside Bore for Primming

START TIME:



Page 1

Dart Aerospace Ltd

W/O:			WO	RK ORDER CHANG	ES		•					
DATE	STEP	PRO	OCEDURE CHAN	NGE		By Date Qty			Approval Chief Eng / Prod Mgr	Approval QC Inspector		
								5				
Part No	:	PAR #:	Fault Categ	jory:	_ NCR:	Yes N	lo DQ .	A:				
	Resolution:		Disposition	1:	_ QA: N	I/C Clo	sed:		Date: _			
NCR:		,	WORK ORDE	R NON-CONFORM	ANCE (NCR))					
DATE		Description of NC			ion B		Verific	cation	Approval	Approval		
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	,	Sign & Date		on C	Chief Eng	QC Inspector		
								•				
										,		

NOTE: Date & initial all entries

Tuesday, 30/09/2008 10:01:51 AM Julie Lecocq User: **Process Sheet** Drawing Name: 02.750 SUPPORT Customer: CU-DAR001 Dart Helicopters Services Part Number: D28931 Job Number: 42353 Job Number: **Description:** Seq. #: Machine Or Operation: **OVEN TEMPERATURE:** FINISH TIME: INSPECT POWDER COAT/CHEMICAL CONVERSION QC3 6.0 Comment: INSPECT POWDER COAT SPRAY PAINTING SPRAY PAINTING 7.0 Comment: SPRAY PAINTING 06-10 2 Prime inside surface as per Dwg D2893 and QSI 005 4.3. QC14 8.0 Comment: INSPECT PACKAGING RESOURCE #1 PACKAGING 1 9.0 Comment: PACKAGING RESOURCE #1 Identify and Stock Location: X FINAL INSPECTION/W/O RELEASE QC21 10.0 Comment: FINAL INSPECTION/W/O RELEASE Job Completion

Dart Aerospace Ltd

Duit Au	. oopaot	Liu									
W/O:			V	VORK OR	DER CHA	ANGES					
DATE	STEP	PROC	EDURE CI	IANGE			Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
			•			-					
						-					
					•		-			•	
					•						
		<u> </u>	· ·						<u> </u>		
Part No	:	PAR #:	_ Fault Ca	itegory:		NC	R: Yes	No DQ	A:	Date: _	
Resolution:			_ Disposi	tion:	•	QA	A: N/C CI	osed:		Date: _	
NCR:		W	ORK OR	DER NON	-CONFO	RMANC	E (NCR)			
DATE	STEP	Description of NC	Initial	Corrective Action Section B itial Action Description			Verifica				Approval
		Section A	Chief Eng	ACU	Chief Eng		Date	Sect	on C	Chief Eng	QC Inspector
					•	,					
i					; ·		•				
					·	·					
						· · · · · · · · · · · · · · · · · · ·	+				
						•			•		
						•					ì

NOTE: Date & initial all entries

DART AEROSPACE LTD	Work Order: 42353
Description: Ø2.750 Support	Part Number: D2893-1
Inspection Dwg: D2893 Rev: B	Page 1 of 1

FIRST ARTICLE INSPECTION DIMENSION SHEET

			ARTICLE IN	Article		otype	•	
			_ FIISL /	41 ticle	<u> </u>			
					Record	d Actual Dim	ensions	
Dim	Min	Max	Go/No Go Gauge	1	2	3	4	5
				HAAS Sect	ion			
AA	2.985	3.005		3.005	3.005	3.005	3.005	3.003
AB	0.440	0.460		. 450	400	.450	.450	.450
AC	0.125	0.160		457	147	.150	.152	152
ΑĐ	0.040	0.060		.050	920	050	.050	.050
AE	0.188	0.193		.188	-188	.798	/88	. 188
AF	0.125	0.160		144	. 144	147	.147_	.149
AG	0.140	0.160		150	.150	:150	.150	150
AH	1.360	1.400		1.378	1.378	1.370	1.370	1.370
Al	0.040	0.060		.050	. 070	.050	050	.050
AJ	1.190	1.230		1.205	1.205	1.205	1.205	1.205
AK	0.010	0.020		015	.015	015	015	1015
ΑĿ	0.053	0.073		,063	.063	,063	063	,563
AM	0.240	0.260		-250	.250	1,250	,250	.250
AN	2.518	2.538		2.530	2.530	2.536	2.536	2.530
AO	84.39	- 90.39		87.39	87.39	87.39	87.39	87.39
AP	0.261	0.266	*.	.262	260	262	-262	.262
AQ	0.053	0.073		063	: 263	,063	v 063	1.063
AR						N.		
AS						,		
AT.			* -					
			Accept/Reject	:				
		. 0 <					· · · / -	/
	Measured	by:│ 🏂 🏳	· · · · · · · · · · · · · · · · · · ·			Date:	08/10	114
-	Audited	hv: a	x 11			Date:	1	112
	Addited	~J· /						// T
Proto	type Approv	/al:				Date:		
Rev	Date (Change					evised by	Approve
A	02.12.13	Vew Issue					I/RF	
	07.05.00	<u> </u>	Danishad			1/1	7 H M	1

KJ/JLM

08.04.21 Reformat

07.05.08 Dimension AP revised

В

Dart Aeı	rospace	e Ltd								
W/O:			W	ORK ORDER CHANGE	ES					
DATE	STEP	PRO	OCEDURE CH	EDURE CHANGE		Ву	Date Qty		Approval Chief Eng / Prod Mgr	Approval QC Inspector
			·							
					-					
Part No	•	PAR #:	Fault Ca	tegory:	NCR:	: Yes N	o DQA:	:	Date: _	
	R	esolution:	Disposit	ion:	QA: N/C Closed:			Date: _		
NCR:		,	WORK OR	DER NON-CONFORMA	NCE	(NCR)		•		
		Description of NC		Corrective Action Section	on B		Verifica	tion	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Section		Chief Eng	QC Inspector

NCR:		WORK ORDER NON-CONFORMANCE (NCR)									
		Description of NC		Corrective Action Section B	Verification	Approval	Approval				
DATE	STEP	Section A		Initial Action Description Sign Chief Eng Chief Eng Da		Section C	Chief Eng	QC Inspecto			
				·							
		,									
					*						
					<u> </u>						
						·					

NOTE: Date & initial all entries

DART AEROSPACE LTD	Work Order:	42353
Description: Ø2.750 Support	Part Number:	D2893-1
Inspection Dwg: D2893 Rev: B		Page 1 of 1

FIRST ARTICLE INSPECTION DIMENSION SHEET

		LIKOI	ARTICLE IN	3FECTION	- DIMENSI	ON SHEE	•	
			X First A	Article	Proto	otype		
					Record	Actual Dim	ensions	
Dim	Min	Max	Go/No Go Gauge	by	72	43	9 4	10 %
				HAAS Secti	on			
ĀA	2.985	3.005		3.003	3.005	3.005	3.002	3,003
AB	0.440	0.460		.450	.450	.450	.450	.450
AC	0.125	0.160		.150	155	155	150	150
AD	0.040	0.060		.050	.046	360.	,046	.046
ΑĒ	0.188	0.193		.788	.188	.188	1.188	188
AF	0.125	0.160		.160	.149	140	140	.140
AG	0.140	0.160		./60	150	.150	.150	-150
AH	1.360	1.400		1.372	1.370	1.370	1.370	1,370
Al	0.040	0.060		.050	,050	070.	.050	-050
AJ	1.190	1.230		1,206	1.206	1,206	1.206	1.206
AK	0.010	0.020		1015	.015	.015	.015	.015
AL	0.053	0.073		. 063	.067	,063	.063	. 263
AM	0.240	0.260	,	,250	.750	. 350	250	1250
AN	2.518	2.538		2.520	2520	2520	2500	2536
AO	84.39	90.39		87.39	87.39	87.39	87.39	87,39
AP	0.261	0.266		. 272	, 262	,262	262	-262
AQ	0.053	0.073		,063	,063	.063	1,063	063
AR								
AS								
AT								
			Accept/Reject					
		06					//	
	Measure	d by:				Date:	08/10/15	
	Audite	d by:	nl		***	Date:	08/10/	17
Proto	type Appro	oval:				Date:	<u> </u>	
			·	<u> </u>			and here	Anna
Rev	Date	Change					evised by	Approved
Α	02.12.13	New Issue				KJ	I/RF	

07.05.08 Dimension AP revised

Reformat

В

08.04.21

DART AEROSPACE LTD	Work Order:	43355
	·	
Description: Ø2.750 Support	Part Number:	D2893-1
Inspection Dwg: D2893 Rev: B		Page 1 of 1

FIRST ARTICLE INSPECTION DIMENSION SHEET

			X First	Article	Proto	type				
				Record Actual Dimensions						
Dim	Min	Max	Go/No Go Gauge	11	12	13	14	15		
	<u></u>			HAAS Section	n					
ĀA	2.985	3.005		02.999	2.999	2.999	2.998	2.999		
ĀΒ	0.440	0.460		0.440	0.440	0,440	0.440	0.440		
AC	0.125	0.160		0.145	0.130	0.130	0.130	0,/30		
AD -	0.040	0.060		0.050	0,050	0.050	0.050	0.050		
ΑE	0.188	0.193		0.189	0.189	0.189	0.183	0.189		
AF	0.125	0.160		0.137	0.140	0.140	0.140	0.140		
AG	0.140	0.160		0.145	0.143	0.143	0.148	6,146		
АН	1.360	1.400		1,3745	1.375	1.377	1.377	1.376		
ΑI	0.040	0.060		0.047	0.048	0.048	0.049	0.049		
AJ	1.190	1.230		1,2135	1,216	1,215	1.216	1,216		
AK	0.010	0.020		0.015	0.015	0.015	0.015	0.015		
AL	0.053	0.073		0.055	0.055	0.055	0.055	0.055		
AM	0.240	0.260		0.250	0.250	0.250	0.250	0.250		
AN	2.518	2.538		2,530	2,530	2.530	2.530	2.530		
AO	84.39	90.39		87.39	87,39	87.39	87.39	87.39		
AP	0.261	0.266		0.261	0.261	0.2Ce1	0.261	0.261		
AQ	0.053	0.073		0.063	0.063	0.063	0.063	0.063		
AR										
AS			·		-					
AT				<u></u>				ļ		
			Accept/Reject		1			<u> </u>		
	Measured b	y: DIT	>			Date:	08/10/16	<i></i>		
	Audited b	ov: 9				Date:	08/10/	/Z		

te: 08/10/17
te:
a

Rev	Date	Change	Revised by Approve	ed
Α	02.12.13	New Issue	KJ/RF	
В	07.05.08	Dimension AP revised	KJ/JLM 14	1
С	08.04.21	Reformat	KJ/JLM 🛠 🗸	

Work Order: DART AEROSPACE LTD Part Number: D2893-1 Description: Ø2.750 Support Inspection Dwg: D2893 Page 1 of 1 · Rev: B

FIRST ARTICLE INSPECTION DIMENSION SHEET									
•			X First A	Article	Proto	type	•	_	
				Record Actual Dimensions					
Dim	Min	Max	Go/No Go Gauge	16	17	18	19	20/13	
		-!		HAAS Section	on				
AA	2.985	3.005	1	3.000	3.000	3.000	3.000	3.099	
AB	0.440	0.460		0.440	0.440	0,440	0,440	0440	
AC	0.125	0.160		0./30	0,130	0.130	0,130	0.130	
AD	0.040	0.060		0,050	0.050	0.050	0.050	0.050	
AE	0.188	0.193		0.189	0,189	0.189	0.189	0.189	
AF	0.125	0.160		0.140	0.145	0,140	0.140	0.140	
AG	0.140	0.160		0.145	0.145	0.145	0.146	0.145	
AH	1.360	1.400	-	1,376	1.376	1.376	1,376	1.37.6	
Al	0.040	0.060		0.047	10.048	0.048	0.048	0.048	
AJ	1.190	1.230		7,215	1.215	1.215	1.216	1.210	
AK	0.010	0.020		0.015	0.015	0.015	0.015	0.015	
AL	0.053	0.073		0.055	0.055	0.055	0.055	0,055	
AM	0.240	0.260		0.250	0.250	0.250	0.250	0,250	
AN	2.518	2.538	<u></u>	2,530	2.530	2.530	2.530	2.530	
AO	84.39	90.39		87.39	87.39	87.39	87.39	87.39	
AP	0.261	0.266		0.261	0.261	0.261	0.26	0,261	
AQ	0.053	0.073		0.063	0.063	0.063	0.063	0.063	
AR					•				
AS									
ΑT									
Accept/Reject									
Measured by: Date: of/10/16									
	Audited by: Date: 08/10/12								
Prototype Approval: Date:									
Rev									
Α									
В									
C 08.04.21 Reformat KJ/JLM KJ/JLM									

